

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.6	33			У
2	7.6	237			y
3	7.5	35			y
4	7.6	38			4
1 2 3 4 5 6 7 8	7,5	33 237 35 <b>38</b> 53			Ý
6	7.5	46			Y Y Y Y Y Y Y Y Y Y
7	7.6 8,0 7.6 7.5 7.4 7.4 7.4 7.5 7.5 7.5	51			y
8	810	52 43 39 48 41 39 38 40 47 48 47 48 47 48 47 48 47 48 47 48 47 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 47 48 48 48 48 48 48 48 48 48 48			У
9	7.6	52			y
10	705	43			4
10 11 12 13 14	7.5	39			Y
12	7.4	48			Y
13	7.4	41			У
14	7,4	39			y
15 16	7.5	38			y
16	7.5	40			y
17	7,5	47			У
18	7,9	48			ý
19	7,5	41			У
20	7,5	52			Y
18 19 20 21 22 23	7,5	4.7			У У У
22	7,5	41			Y
	7,5	377			Y
24	715	44			У
25	7.6	42			Y
26	115	36			Y
27	7,6	43			Y
28	110	35			4
29	7,5	31			Y
30	7.6	37	- 4		4
31	7.6	41			ý
lo = N = Excursion) <b>Total N's</b>			0		

< <have< th=""><th>County: Hood River Agency: HOOD RIVER COUNTY</th></have<>	County: Hood River Agency: HOOD RIVER COUNTY					
minimums	ENTRY POINT EP-A					
been met for this day?						
PWS ID 4100172						
CASCADE LOCKS, CITY OF						
Sample period: 10 22  Month/Year						

Number of excursions during this month: \_\_\_\_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference -						
Minimum Water Quality Parameter(s) as set by State:						
pH Alk	7.0 31.0	(Alkalinity)				
	ı					

Print Name: Sheldon P	rica
Signature: Shorton R	vien .
Date & Phone#: 541-99	0-5610 11/3/22

Send to DWP within 10 days after end of

sampling period